

**Errata**

The following editorial correction has been found in Vol.E103-A, No.12, and should be corrected as follows.

Wrong terms	to be corrected as
p.1647 right column 18th line from the bottom ... This however this results in an increase in the power dissipation of the sensing unit owing to the additional implementation of the MPU. ...	p.1647 right column 18th line from the bottom ... This results in an increase in the power dissipation of the sensing unit owing to the additional implementation of the MPU. ...